

NO

IMAG AVAILABL

AASBC-541

2600 MHz | Same Band Combiner | AISG and DC Transparency | Single Unit

- 2600 MHz, antenna sharing filter
- AISG and DC transparency
- Helps to minimize site acquisition issues
- Reduces the cost of network expansion

RF Characteristics				
Uplink (Rx) Path		Low	High	
Frequency Band		2500-2520 MHz	2530-2570 MHz	
Insertion Loss		< 0.65 dB	< 0.65 dB	
Downlink (Tx) Path		Low	High	
Frequency Band		2620-2640 MHz	2650-2690 MHz	
Insertion Loss		< 0.75 dB	< 0.75 dB	
Continuous Average Power	Average (53 dBm)	200 W		
	Peak (57 dBm)	500 W		
Intermodulation (2x43 dBm TX carrier, BTS Port)		-160 dBc		
All Bands				
Return Loss		18 dB.		
Isolation Between Node B Ports	at Rx Frequency	20 dB		
	at Tx Frequency	35 dB		
Power Supply				
AISG Signal Attenuation at 2,176 GHz		< 1 dB		
Voltage Drop (maximum at 10-30 VDC)		1 V		
Supply Voltage Handling		0-32 VDC		
Continuous Current Handling		5A, 0-32 VDC		
AISG / DC Transparency Between Ports		High to Common		
Environmental Charac	teristics			
Operating Tem perat ure Range		-10° to +65° C (+14° to +149° F)		
Operation		ETS 300 019-1-4 Class 4.2H		
Storage		ETS 300 019-1-1		
Ingress Protection		IP67		
EMC		EN 301 489-8		
Safety Standards		EN 60950		
MTBF		1.5 M hours		
Lightning Protection		3 kA 10/350 μs, 10 kA 8/20 μs		

Quoted performance parameters are provided to offer typical or range values only and may vary as a result of normal manufacturing and operational conditions. Extreme operational conditions and/or stress on structural supports is beyond our control. Such conditions may result in damage to this product. Improvements to product may be made without notice.



AASBC-541

2600 MHz | Same Band Combiner | AISG and DC Transparency | Single Unit

Mechanical Characteristics					
Dimensions - Length x Width x Depth	230 x 180 x 55 mm	9.1 x 7.1 x 2.2 in			
Connectors (number, type)	3 Connectors / 7-16 Female				
Block Diagram					
Common					

Quoted performance parameters are provided to offer typical or range values only and may vary as a result of normal manufacturing and operational conditions. Extreme operational conditions and/or stress on structural supports is beyond our control. Such conditions may result in damage to this product. Improvements to product may be made without notice.